

SECRET

OUT58397

SECRET 030132Z

1966 MAY 3 01 44Z

7086

25X1

CAMERA B 7 WAS USED IN MISSION 8089 FLOWN ON 29 APRIL 1966. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

1. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: THE TITLING ON FRAMES 1 AND 2 ARE SMEARED. THERE IS A MANUFACTURING SPLICE AND AN ADJACENT FOGGED AREA IN FRAME 420. THERE IS A HEAT SPLICE THROUGH FRAME 1267.

C. 9L SIDE: MINOR EDGE STATIC AND EDGE FOG OCCURS INTERMITTENTLY THROUGHOUT THE MISSION. VERY MINOR ROLLER CHATTER IS PRESENT ALONG THE INBOARD EDGE. A HEAT SPLICE WAS MADE BETWEEN FRAMES 269/270 AND THROUGH FRAME 1252. A MANUFACTURING SPLICE IS LOCATED BETWEEN FRAMES 1531/1532.

D. THE FRAME COUNTER SKIPPED NUMBER 002. THE LAST TITLED FRAME IS 2556.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

2. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS DEGRADE OR OBSCURED 40 PERCENT OF THE MISSION.

SECRET

/END OF MESSAGE/

3 MAY 1966

ADMIN	
SIG ER	
PAGES	
QID	
IFD	
FD	
FSD	
FSD-HCS	
TID	
IAD	
PAG	
DIAXX-4	
SPAD	
USA-LO	
DIA-67	

SOURCE: [REDACTED]
SOURCES**SECRET**GROUP 1
Excluded from automatic
downgrading and
declassification